



607 Industry Rd. • P.O. Box 2287  
Louisville, KY 40201-2287  
(502) 634-4753 • FAX/634-4757

Humboldt, Tennessee  
Warehouse Manager: Charles Cheatham

Physical Address: *Phone: (731) 784-7130*  
965 Mullins St.  
Humboldt, TN 38343 *Fax: (731) 784-6621*

Mailing Address:  
965 Mullins St.  
Humboldt, TN 38343

### **Humboldt Warehouse**

Our Humboldt, Tennessee facility is located in the heart of rural West Tennessee in Gibson County. Gibson is central to major State Highways 45 and 70/79 and Interstate Highway 40 making this area a popular home for several truck lines. Add easy access by rail and air and Gibson County forms an excellent network of transportation for its citizens and its industries.

The Humboldt warehouse is a one-story brick, concrete, and panel warehouse with total refrigerated space of 2,151,000 cu. ft. including total cooler space of 530,000 cu. ft. The warehouse is configured to accommodate a variety of products with different temperature needs ranging from -25°F to +55°F. In addition, we have blast freezing capacity at this location of 100,000 lbs per day. For protection of your product, this facility is fully racked with approximately 6,877 pallet positions. We track your product with computerized inventory control and EDI. Dry storage space is available if needed.

Our Humboldt dock is fully enclosed with six truck doors and two rail doors. Our rail car siding can accommodate four cars and is serviced by Norfolk Southern, CSX, and West Tennessee RR.

The safety and quality of your product is very important to us. We have received a superior rating from the American Sanitation Institute (ASI) in excess of five consecutive years. Systems Unlimited provides 24-hour centralized monitoring of our sprinkler, refrigeration, and burglar alarm systems.

#### **Directions**

##### **From IH-40**

From IH-40 take Exit 80 (Highway 45 north) into Humboldt. Continue on Hwy 45 north to the fourth traffic light (Central Avenue). Turn left onto Central and continue to the first street on the right (West Mullins). Turn right onto West Mullins and American Cold Storage is the first warehouse on the right.

##### **From US Hwy 51**

From US Hwy 51, take State Highway 412 south to State Highway 79 east. From State Highway 79 east, take the 45 Bypass to the first traffic light. Turn right at the light onto Central Avenue, and then turn right onto West Mullins St. (first street to right). American Cold Storage is the first warehouse on the right.

##### **From IH-65**

From IH-65, take IH-40 west to Exit 80 (Highway 45 north) into Humboldt. Continue on Highway 45 north to the fourth traffic light (Central Avenue). Turn left onto Central and continue to the first street on the right (West Mullins). Turn right onto West Mullins and American Cold Storage is the first warehouse on the right.

##### **From IH-55**

From IH-55 take IH-155 to US Hwy 51. From US Hwy 51, take State Highway 412 south to State Highway 79 east. From State Highway 79 east, take the 45 Bypass to the first traffic light. Turn right at the light onto Central Avenue, and then turn right onto West Mullins St. (first street to right). American Cold Storage is the first warehouse on the right.